QUALITY CONTROL

Name of the Work:	Providing and Construction of culverts at Kammagondanahalli area in w.No.12
Job No:	012-11-000064
Work order No:	349/15.02.2013
BR No:	307/31.08.2013

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed Two / Three years back.

28/8

Assistant Executive Engineer
Shettyhalli Sub Division
Bruhat Bengaluru Mahanagara Palike

Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike